AGRICULTER DE

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

Reason For Inspection:

1st Weekly

2nd Weekly

											DATE:	05/31/11
State Rout	te (SR) / US Ro	ute or Road N	ame and D	escription:			Are correc	tive actions	required by	this inspe	ction report (Y/N):	T
	Wolf River Blvd.								Ye	es		
County(ies	;):	TDOT PIN:		NPDES P	ermit (NOC)) #:	Number of	New	Number of	Recurring	Number of New	Number of Un-Corrected
5	Shelby	1016	515		TNR15329		Corrective		Corrective		Sediment Releases:	Sediment Releases:
TDOT Con	struction No.:	TDOT Contra	act No.:	Contractor	:	479-047	1 .	7		0	0	0
7994	1-1535-54			Acuf	f Enterprise	s Inc.		ı		J		0
	der penalty of law					Consultan	t EPSC Insp	pector and 1	Title (print o	type):	Signature:	0
designed to information	assure that quali presented. Base	ified personnel ed on my inquiry	properly gath of the perso	nered and ev on or persons	aluated who			ald "Jerry" S	0.000		Serall.	Stanfor
manage the system, or those persons directly responsible for gathering the information, I cerify that inspections of storm water discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in the table above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as							Tom Acuff			Signature:	land	
recorded in the table above. I am aware that there are significant penalties for submitting false information, including the possibility of fine and impresonment for knowing violations.					TDOT Project Supevisor / Designee and Title Signature: (print or type):							
		TDOT EPSO	C Inspectio	n Weekly F	Rainfall Dat	ta Log						
		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	(200 8)		tractor Agrees with In	spection Report:
Date	Day of Week		Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO	or (YES)	
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, expl	ain and initial:	
	Sunday				N/A	N/A	N/A	N/A		<u> </u>		
5/30/11	Monday	0%			N/A	N/A	N/A	N/A		21	ams frem	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
5/31/11	Tuesday	20%	0	0	N/A	N/A	N/A	N/A		2-1-	at Thus	Timo.
6/1/11	Wednesday	10%			N/A	N/A	N/A	N/A				V
6/2/11	Thursday	10%			N/A	N/A	N/A	N/A				
5/27/11	Friday	10%	0	0	N/A	N/A	N/A	N/A				
5/28/11	Saturday	20%			N/A	N/A	N/A	N/A				
5/29/11	Sunday	10%			N/A	N/A	N/A	N/A		1,12		

Predicted Precipitation Source:

Monday

www.weather.com

N/A

N/A

N/A

N/A

Page 1 of 6

(Additional pages may be attached, if needed)

	i OV	HE	57%	•.
	2	X	*	9
E C	AGRI	*	Z /	
.//		796		/

State/US Route or Road Name	State/U	S Route	e or Road	Name
-----------------------------	---------	---------	-----------	------

Wolf River Blvd. TDOT Construction No.: 79954-3537-54

79954		

TDOT Contract No.:

Date	5/31/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	5/23/2011		22	S	STABLE (NO ACTION NEEDED)
1A	1	21+50	RT	5/31/2011	T=3-25-11	16,24,33,35	С	The sediment needs to be removed from SFB. Remove wattle from stream as seen in photo report.
1B	1	22+00	RT	5/31/2011	T=3-25-11	16,33,35,24	1	Additional wattles needed as shown in photo report.
1C	1	21+00	LT	5/31/2011	T=3-25-11	10,12,16,24,33,35	C,I	Filler bag replaced(5-31-11) Floatable debris needs to be removed from stream. RSS needs to be installed as seen in photo report.
2A	1	33+50	RT	3/25/2011	T=3-25-11	16,33	FM	The damaged SFB will need to be repaired before work begins. See photo.
2B	1	35+50	RT	3/25/2011	T=3-25-11	16,33	S	STABLE (NO ACTION NEEDED)
3	1	34+50	LT				S	The area has not been disturbed.
4	1	40+00	RT				S	The area has not been disturbed.
5A	1	49+00	RT				S	The area has not been disturbed.
5B	1	50+00	RT				S	The area has not been disturbed.

EROSION AND SEDIMENT CONTROL MEASURE CODES

	EROS	ION A	ND SEDIMENT CONTROL MEASUR	E COD	ES		CONDITION CODES
1	Temporary Silt Fence / Filter Barrier	15		29	Excess Dirt Removed from Rdwy, Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dessipater	35	Sediment Tube	W	Too Wet to Work Condidtions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, reprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	

	THE STATE OF THE S	
1	AGRICULTURE	1
	ALKIEUTURE I)
1	OHMENC 1796	•

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	5/31/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT				s	The area has not been disturbed.
6	1	56+00	LT				S	The area has not been disturbed.
7	1	60+00	RT				S	The area has not been disturbed.
8A	1	73+00	RT				S	The area has not been disturbed.
8B	2	75+50	RT				S	The area has not been disturbed.
8C	1	71+00	LT				S	The area has not been disturbed.
8D	2	75+50	LT				S	The area has not been disturbed.
8E	1	71+50	LT				S	The area has not been disturbed.
9A	2	80+00	RT	5/31/2011	T=5-31-11	16	S	STABLE (NO ACTION NEEDED)
9B	2	80+00	LT	5/31/2011	T=5-31-11	16	1	Wattles need to be installed as seen in photo report.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1 Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 4 18 Flexible Channel Liner 32 Rock Silt Screen Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Sill Fence with Backing C Cleaning Needed Riprap Outlet Structure 6 Sediment Removal 20 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dessipater 35 Sediment Tube W Too Wet to Work Condidtions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin 9 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release SR 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, reprap, rock) Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap Other (O31): ____ 26 Temporary Stream Diversion 40 Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Other (O#2): 41 Haul Road 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade 42 Other (O#3):

CONDITION CODES

•:•	THE	5×.
	23	
	GRICUIT	URE E
	OMMER 1796	

State/US Route or Road	Name	É
------------------------	------	---

	n.	DI 1
WWOIT	River	RIVA

TDOT Construction No.: 79954-3537-54

79954	

TDOT	Contract No.:	
1001	CONTRACT NO.	


Date	5/31/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	5/31/2011	T=5-31-11	16	S	STABLE (NO ACTION NEEDED)
10A	2	85+00	RT	5/31/2011	T=5-31-11	16,24	S	Contractor is currently installing temp. crossing and mulch.
10B	2	85+00	RT	5/31/2011	T=5-31-11	16,24,35	S	Contractor is currently installing temp. crossing and mulch.
10C	2	85+50	LT	5/31/2011	T=5-31-11	16,35	S	STABLE (NO ACTION NEEDED)
10D	2	84+50	LT	5/31/2011	T=5-31-11	16,35	S	STABLE (NO ACTION NEEDED)
11A	2	92+50	RT	5/31/2011	T=5-31-11	16,24,35	I	Install wattles as seen in photo report.
11B	2	92+50	LT	5/31/2011	T=5-31-11	10.16,35	FM	Area around filter bag will need to be dressed and stabilized as necessary.
11C	2	92+00	LT	5/31/2011	T=5-31-11	16,35	1	Install wattles as seen in photo report.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdvy. Daily Temporary Diversion Berm or Ditch 2 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing 33 С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dessipater 35 Sediment Tube W Too Wet to Work Condidtions Sand Bags 8 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin Temporary at Construction Exit / Entrance 23 Concrete Washout, other pollution Issues Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, reprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom Gabion 39 S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion Sheet Pilling Other (O31): Other (O#2): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Permanent Seeding with Mulch or Sod 14 28 Mineral Aggregate Base on Subgrade 42 Other (O#3):

CONDITION CODES






Outfall 1C Sta. 21+00 LT The floatable debris needs to be removed from stream. (C)



Outfall 1C Sta. 21+00 LT A RSS needs to be installed as shown. (I)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Outfall 11A & 11C Sta. 92+00 thru 92+50 LT/RT

Install wattles as seen in photo. (I)



(FM) Dress and stabilize area before filter bag is used. Outfall 11B Sta. 92+50 LT

Not Used



City of Germantown 1920 S. Germantown Road Germantown, TN 38138